

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403483492

Date Received:

08/01/2023

## FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

ERIN JOSEPH

Phone

970-515-1169

Email

COGCCInspections@Oxy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 694100121

Inspection Date: 07/13/2023

FIR Submit Date: 08/01/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

### LOCATION - Location ID: 329818

Location Name: MARKHAM-64N68W Number: 15NESW County: \_\_\_\_\_

Qtrqtr: NESW Sec: 15 Twp: 4N Range: 68W Meridian: 6

Latitude: 40.310444 Longitude: -104.992953

### FACILITY - API Number: 05-123-00 Facility ID: 329818

Facility Name: MARKHAM-64N68W Number: 15NESW

Qtrqtr: NESW Sec: 15 Twp: 4N Range: 68W Meridian: 6

Latitude: 40.310444 Longitude: -104.992953

### CORRECTIVE ACTIONS:

1 CA# 176925

Corrective Action: Stained soil identified at various locations through out location. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D

Date: 08/08/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

METER HOUSE IS OWNED AND OPERATED BY WES

Operator  
Comment:

COGCC Decision: **Not Approved**

COGCC  
Representative:

Operator remains responsible for the removal of all equipment on their Locations, regardless of ownership, in accordance with 1004 Rules. It is ECMC's expectation that Operator will work with the Owner to remove and cleanup all equipment from the Location, to allow Operator to bring the Location back into compliance.

COGCC  
Supervisor:

Operator remains responsible for the removal of all equipment on their Locations, regardless of ownership, in accordance with 1004 Rules. It is ECMC's expectation that Operator will work with the Owner to remove and cleanup all equipment from the Location, to allow Operator to bring the Location back into compliance.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: \_\_\_\_\_

Title: SR REGUALTORY ADVISOR

Date: 8/1/2023 2:31:29 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403483492	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files