

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107154

FIELD INSPECTION FORMLoc ID 331882 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267813	WELL	PR	03/01/2022	GW	123-21441	LOST CREEK 5	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation around the well needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 09/22/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 267813 Type: WELL API Number: 123-21441 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/01/2021

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403257040 indicates it was last tested on 12/8/20.

09/22/2023

Corrective Action: Submit reports as per Rule 207.

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 8/8/23 at approximately 1012hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lost Creek 5 of O'Brien Energy Resources Corp. API #05-123-21441 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Overgrown vegetation around the well needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>No updated annual BH test on file. Submit reports. Form 17 #403257040 indicates it was last tested on 12/8/20. Submit reports as per Rule 207. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	08/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107155	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213442