

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2023

Submitted Date:

08/03/2023

Document Number:

699107064

**FIELD INSPECTION FORM**

Loc ID 317961 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
317961	LOCATION	AC			-	LYLE V. COOKSEY GAS UNIT-62N64W 18SENE	SI

**General Comment:**

[This is an inspection on the tank battery](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Capacity label on the pit is unreadable and needs replaced. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	08/25/2023
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Adequate		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds grown in the berm for the production tanks need to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	08/25/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbwire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	

PRODUCED WATER	1		PBV FIBERGLASS			
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.141000,-104.586500	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 317961 Type: LOCATION API Number: - Status: AC Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI tank battery

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      On Wednesday 8/2/23 at approximately 1013hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lyle V. Cooksey Gas Unit 1 Tank Battery of Chevron. Location ID #317961 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Capacity label on the pit is unreadable and needs replaced. Install sign to comply with Rule 605.g. With a Corrective Action date of 8/25/23                      Weeds grown in the berm for the production tanks need to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 8/25/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	08/03/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403485595	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6205769">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6205769</a>
699107065	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6205729">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6205729</a>