

Location			
Lease Road:			
Type	Access		
comment:	Overgrown vegetation on the access road, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation around the well, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241624 Type: WELL API Number: 123-09413 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 10/11/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday 8/10/23 at approximately 1240hrs I, Inspector Adam Burns, Conducted an on-site inspection at Jerry 1 of KP Kauffman Company Inc. API #05-123-09413 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Overgrown vegetation on the access road, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23 Overgrown vegetation around the well, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	08/10/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107191	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215237