

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403495447

Date Received:  
08/14/2023

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Heibel, Krystal

ellen54ward@gmail.com

krystal.heibel@state.co.us

Bongers, Brent

361-935-5633

bbongers@impetroresources.com

### OGCC INSPECTION SUMMARY:

FIR Document Number: 708200451

Inspection Date: 08/03/2023

FIR Submit Date: 08/11/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: WARD & SON\* ALFRED

Company Number: 94300

Address: P O BOX 737

City: OGALLALLA State: NE Zip: 69153

### LOCATION - Location ID: 312310

Location Name: STATE-611N53W Number: 23NWNW County: \_\_\_\_\_

Qtrqr: NWN Sec: 23 Twp: 11N Range: 53W Meridian: 6

Latitude: 40.918244 Longitude: -103.263648

### FACILITY - API Number: 05-075- -00 Facility ID: 312310

Facility Name: STATE-611N53W Number: 23NWNW

Qtrqr: NWN Sec: 23 Twp: 11N Range: 53W Meridian: 6

Latitude: 40.918244 Longitude: -103.263648

### CORRECTIVE ACTIONS:

1 ☒ CA# 178217

Corrective Action: Gas leak at stuffing box: 24 hrs (08/12/2023) to fix leak or isolate leak.

Date: 08/26/2023

Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e; (08/26/2023)

Response: CA COMPLETED

Date of Completion: 08/12/2023

Operator Comment: Operator repaired, greased and tightened the stuffing box. Gas leak was verified to be fixed by spraying soapy water, and through visual/audible check.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Donahue

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 8/14/2023 10:18:36 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

403495447	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files