

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403119686

Date Received:  
08/07/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 97730  
Name of Operator: WYMAN\* LOUIS M DBA WYMAN INC  
Address: P O BOX 278  
City: CRAIG State: CO Zip: 81626

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>wyman, David</u>	<u>970-701-9388</u>	<u>brokenbox6431@yahoo.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800386  
Inspection Date: 06/29/2022 FIR Submit Date: 07/13/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: WYMAN\* LOUIS M DBA WYMAN INC Company Number: 97730  
Address: P O BOX 278  
City: CRAIG State: CO Zip: 81626

LOCATION - Location ID: 313012

Location Name: WECO-UPRC KLEITZ 23-29-67N92W Number: 29NESW County: \_\_\_\_\_  
Qtrqr: NESW Sec: 29 Twp: 7N Range: 92W Meridian: 6  
Latitude: 40.527087 Longitude: -107.746275

FACILITY - API Number: 05-081-00 Facility ID: 313012

Facility Name: WECO-UPRC KLEITZ 23-29-67N92W Number: 29NESW  
Qtrqr: NESW Sec: 29 Twp: 7N Range: 92W Meridian: 6  
Latitude: 40.527087 Longitude: -107.746275

CORRECTIVE ACTIONS:

1 CA# 163323

Corrective Action: Provide documentation, attached to a Field Inspection Report Resolution (FIRR), indicating that the tanks on Location belong to the Surface Owner and if previously utilized for oil and gas operations have been cleaned of hazardous materials.

Date: 07/27/2022

Response: CA COMPLETED Date of Completion: 07/27/2022

Operator Comment: Owner of the property removed tanks (cleaned tanks for water storage for livestock) from site.

COGCC Decision: **Not Approved**

COGCC Representative: The corrective action has already been responded to by the CECMC in the previous FIRR (document #: 403131944).

2  CA# 163324

Corrective Action: Install or repair required BMPs to stabilize the cut slope per Rule 1002.f. Date: 08/10/2022

Response: CA COMPLETED Date of Completion: 10/26/2022

Operator Comment: We have a dozer working on it at the moment and expect it to be regraded and seeded by 8/10/2022. Seeded on 8/10/2022 and again on 10/26/2022. Earthwork is complete

COGCC Decision: **Not Approved**

COGCC Representative: CECMC cannot accept "Corrective Action Completed" for future work to be completed. It is unclear whether seeding dates reflect current or previous timelines, since re-grading is still in process.

OPERATOR COMMENT AND SUBMITTAL

Comment: Property owner removed tanks (cleaned tanks used for water storage for livestock) from the wellsite. Dirt work is ongoing and is expected to be completed by 8/10/2022.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David Wyman Signed: \_\_\_\_\_

Title: Manager Date: 8/7/2023 11:11:18 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403119686	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files