

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2023

Submitted Date:

08/16/2023

Document Number:

694500584**FIELD INSPECTION FORM**Loc ID 316765 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                   | Comment |
|-----------------|-------|-------------------------|---------|
| Trujillo, Helen |       | htrujillo@rlbayless.com |         |

**General Comment:**

On 8/3/23, C-ECMC staff, Kris Neidel was on location to observe Bayless Environmental Contractor collect samples to demonstrate compliance with Location abandonment rules. HRL Environmental staff, Joel Adams was present. Surface owner representative and backhoe operator, Rick Sanny was present. The following areas were investigated with a backhoe and sampled with a hand auger; tank battery, wellhead, treater. The pit was sampled with a hand auger. The Tank Battery had apparent impacted soil. The welded plate was exposed at the wellhead and sampled below cap. Metal debris is still present on the location the following areas; in excavation on NE side of pad, piping leads to the pit on the east side of pad. Random Trash was observed as; pop bottles, tread protectors, etc. Corrective Actions: Remove all debris and Trash, Submit results of samples on Form 27 for Project #30484. It is suggested that the operator plan on delineating the location with an appropriate size rig for rocky conditions. See attached Photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

|                    |  |  |                  |
|--------------------|--|--|------------------|
| Type               | DEBRIS   |  |                  |
| Comment:           | Random Trash was observed as; pop bottles, tread protectors, etc |  |                  |
| Corrective Action: | Remove all debris and Trash                                      |  | Date: 08/30/2023 |

Overall Good: ☐**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403499384    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6221121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6221121</a> |
| 694500585    | photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6221120">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6221120</a> |