



December 1, 1966

Horizon Oil and Gas Company
P. O. Box 7
Spearman, Texas

Gentlemen:

Although we realize there is a question that we do not have jurisdiction over the surface of wells that have been abandoned, we feel responsible to advise operators when we find locations that have been left in an unsightly manner, we pursue the corporation in having these locations cleaned up.

In this regard, we have recently inspected the following wells and found that the pits had not been filled nor the location levelled:

B-1-34 Lepel, Sec. 34, T31S, R44W
#1-19 Griffith "A", Sec. 19, T32S, R43W
#1-B McGinnis, Sec. 8, T32S, R44W
#1-15A Homsher, Sec. 15, T33S, R42W
#1-27 Smith, Sec. 27, T33S, R45W
#1 Shawnee, Sec. 21, T32S, R43W

Would you please advise when you anticipate having these locations cleaned up, or if not, why not.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION
OF THE STATE OF COLORADO

William R. Smith, Deputy Director

WRS:lf