



COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 009 - 6079		LEASE NAME: HAMILTON #1	
LOCATION: NESW34-345-41W		OPERATOR: DON JACKSON	
DATE: 2-20-97		INSPECTOR: R. Vansickle	
Insp. Type: PR	Insp. Status: PR	PA: Y <input checked="" type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> P F Viol.: Y <input checked="" type="radio"/> N NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	✓	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	None	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	Around site.	
Tank Battery Equipment (Rule 603.b.3, 604)	Pmpg unit, sep, GMR, 100BBL with th. ✓	
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)	None ✓	
General Housekeeping (Rule 603)	OK	
Spills (Oil/Water) (Rule 907)	None	
Bradenhead (Rule 207.b)	—	
Drilling Well/Workover (Rule 317)	—	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	—	
Miscellaneous	—	

FEB 25 1997

CORRECTIVE ACTION REQUIRED: None

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.