

**FORM**  
**17**  
Rev  
11/20

**State of Colorado**  
**Energy & Carbon Management Commission**



Document Number:  
403511874

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

**BRADENHEAD TEST REPORT**

Step 1. Before opening any valves, record all tubing and casing pressures as found.  
 Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at <http://cogcc/reg.html#/opguidance>  
 Step 3. Conduct Bradenhead test.  
 Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.  
 Step 5. Submit sample analytical results via Form 43.

1. OGCC Operator Number: 10112      3. BLM Lease No: COD 153758  
 2. Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
 4. API Number; 05-081-07138-00      5. Multiple completion?     Yes     No  
 6. Well Name: LION GOVERNMENT      Number: 9  
 7. Location (QtrQtr, Sec, Twp, Rng, Meridian): SWNE,26,12N,101W,6  
 8. County MOFFAT      9. Field Name: HIAWATHA WEST  
 10. Minerals:     Fee     State     Federal     Indian

11. Date of Test: 08/12/2023  
 12. Well Status:     Flowing  
 Shut In     Gas Lift  
 Pumping     Injection  
 Clock/Intermitter  
 Plunger Lift  
 13. Number of Casing Strings:  
 Two     Three     Liner?

**14. EXISTING PRESSURES**

Record all pressures as found	Tubing: <u>260</u> Fm: _____	Tubing: _____ Fm: _____	Prod Csg <u>310</u> Fm: _____	Intermediate Csg: _____	Surf. Csg <u>0</u>
-------------------------------	---------------------------------	----------------------------	----------------------------------	----------------------------	-----------------------

**BRADENHEAD TEST**

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.  
 Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper  
 Describe fluid type in "Bradenhead Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____ _____	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:
	00:00	260		310		NO FLOW	NONE
	05:00	260		310		NO FLOW	NONE
	10:00	260		310		NO FLOW	NONE
	15:00	260		310		NO FLOW	NONE
	20:00	260		310		NO FLOW	NONE
	25:00	260		310		NO FLOW	NONE
	30:00	260		310		NO FLOW	NONE
REQUIRED - Instantaneous Bradenhead Pressure at End of Test: <u>0</u> PSIG							

## INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Intermediate Fluid" column: H = Water H<sub>2</sub>O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None.

	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:	
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No	00:00							
Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	05:00							
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	10:00							
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____	15:00							
	20:00							
	25:00							
	30:00							
REQUIRED - Instantaneous Intermediate Casing Pressure at End of Test: _____							PSIG	

Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: Doug Palmer Title: Pumper Phone: (307) 264-9990

Signed: Afton liams Title: HSE/Regulatory Technician Date: 8/28/2023

Witnessed By: \_\_\_\_\_ Title: \_\_\_\_\_ Agency: \_\_\_\_\_