

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2023

Submitted Date:

08/22/2023

Document Number:

699107280

**FIELD INSPECTION FORM**

Loc ID 330074 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email         | Comment                         |
|--------------|-------|---------------|---------------------------------|
|              |       | cogcc@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 250552      | WELL | PR     | 03/01/2019  | GW         | 123-18355 | HSR-HOBE STATE 2-32 | SI          |

**General Comment:**

This is a follow up to prior inspection documents #699106912 & #699107136. CA hasnt been corrected

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |          |       |  |
|--------------------|----------|-------|--|
| Comment:           | Adequate |       |  |
| Corrective Action: |          | Date: |  |

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | Stained soil next to the well needs to be removed. See attached photo |       |            |
| Corrective Action: | "Properly dispose of oily waste in accordance with 905.e."            | Date: | 07/21/2023 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 250552 Type: WELL API Number: 123-18355 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/23/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p><a href="#">ECMC Inspection Report Summary</a><br/>                     On Monday 8/21/23 at approximately 1027hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699106912 &amp; #699107136 at HSR-Hobe State 2-32 of KP KAUFFMAN COMPANY INC. API #05-123-18355 in Weld County, Colorado.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     Stained soil next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 7/21/23<br/>                     A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.<br/>                     This is a summary of the inspection report.</p> | burnsa | 08/22/2023 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403505439    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6228218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6228218</a> |
| 699107281    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6228184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6228184</a> |