

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403518263

Date Received:
09/01/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>General</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 712700560
Inspection Date: 08/21/2023 FIR Submit Date: 08/21/2023 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306779

Location Name: ANDERSON-N32N6W Number: 5SWSW County: LA PLATA
Qtrqr: SWS Sec: 5 Twp: 32N Range: 6W Meridian: N
Latitude: 37.042120 Longitude: -107.528810

FACILITY - API Number: 05-067- -00 Facility ID: 264621

Facility Name: ANDERSON Number: 1 (1R)
Qtrqr: SWS Sec: 5 Twp: 32N Range: 6W Meridian: N
Latitude: 37.042120 Longitude: -107.528810

CORRECTIVE ACTIONS:

1 ☒ CA# 179138

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 09/10/2023

Response: CA COMPLETED

Date of Completion: 08/31/2023

Operator Comment: Rebuilt / repaired the berm wall. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 179139

Corrective Action: Remove debris from containment to comply with Rule 606.

Date: 09/05/2023

Response: CA COMPLETED

Date of Completion: 08/31/2023

Operator
Comment:

Removed empty container and other trash from within the containment. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 179140

Corrective Action: Install proper guy line markers per Rule 1003.a or remove if non-servicable or not needed for ongoing operations.

Date: 09/04/2023

Response: CA COMPLETED

Date of Completion: 08/31/2023

Operator
Comment:

Installed new guy line anchor marker. See attached photos.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 9/1/2023 8:55:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403518263	FIR RESOLUTION SUBMITTED
403518278	ANDERSON 1R_712700560_Resolved Photos

Total Attach: 2 Files