



00650801

rec file

XXXXXXXXXX
XXXXXX

February 13, 1963

Mr. N.A. Brethouwer, M.D.
Montrose Medical Center
700 Main Street,
Montrose, Colorado

Dear Mr. Brethouwer:

We realize that you have been placed in an unwanted situation with the No. 1 Stiner well.

Until this well is properly plugged or a bond taken out by another person to cover the well, your bond must remain in effect.

It is our understanding that a Mr. Walter Broadhead was to pull some of the casing and plug the well. To our knowledge, this has not been done.

Enclosed are the forms that are required after a well has been drilled and plugged.

Very truly yours,
OIL AND GAS CONSERVATION COMMISSION

D.V. Rogers, Director

DVR:LD
Enc: OGCC-5 & 6