

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/24/2023

Submitted Date:

08/31/2023

Document Number:

713600144

### FIELD INSPECTION FORM

Loc ID 324831 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 383 INVERNESS PKWY, STE 360  
City: ENGLEWOOD State: CO Zip: 80112

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BEAR STACY		stacy@strachanexploration.com	
HARMS JASON		jason@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213004	WELL	PR	06/01/2022	OW	061-06365	FRAZEE 2-6	RI

**General Comment:**

On 8/24/2023, Ryan Costa conducted a follow up location inspection.  
See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

	Type TANK LABELS/PLACARDS		
Comment:	The labeling on the tanks is faded and/or missing. Corrective action will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/29/2023

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:  The oily sludge previously observed has been cleaned up.

Multiple Spills and Releases?

**Fencing/:**

Type TANK BATTERY

Comment: The fence around the tanks and production equipment is inadequate to prevent livestock entry. Corrective action will remain out of compliance until completed.

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 06/29/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	6				
Comment:	There is an open top tank filled with oily fluids that does not have complete netting covering the top to prevent wildlife entry. Corrective action will remain out of compliance until completed.				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 08/24/2023

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	There are two large volume tanks with no labeling and no secondary containment. Corrective action will remain out of compliance until completed. If the tanks are not in use then unused equipment needs to be removed per Rule 606.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 06/29/2023

**Venting:**

Yes/No

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403516929	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238225">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238225</a>
713600145	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238210</a>