

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2023

Submitted Date:

08/17/2023

Document Number:

713300018

**FIELD INSPECTION FORM**Loc ID 318857 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		COGCC@KPK.com	<a href="#">All Inspections</a>
Silver, Randy		randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242321	WELL	SI	05/01/2021	OW	123-10112	WATTENBERG, HENRY E. UNIT C-1	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	electric service to prime mover removed, pumping unit is considered unused equipment		
Corrective Action:	Comply Rule 606	Date:	09/17/2023
Type	OTHER		
Comment:	Mechanical issues, no electrical service to motor		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 09/17/2023
Type	WEEDS		
Comment:	Overgrown vegetation		
Corrective Action:	Rule 606	Date:	09/17/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electrical control panels		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 242321 Type: WELL API Number: 123-10112 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.Date: 09/17/2023**BradenHead**Date of Last Brhd Test: 08/22/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 8-17-23 at approximately 12:30, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: Wattenberg Henry E Unit C#1</p> <p>Operator: KP Kaufman</p> <p>API#: 123-10112</p> <p>County: Weld</p> <p>While there, I observed shut in well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds; Rule 606 corrective action date 9-17-23 See photo 2</p> <p>Mechanical issues: rule 608E corrective action date 9-17-23 See photo 4</p> <p>Unused equipment: Rule 606 corrective action date 9-17-23 See photo 3 &amp; 4</p> <p>MIT; Rule 417B corrective action date 9-17-23</p> <p>Weather conditions: Dry &amp; Clear</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p>	kesterm	08/17/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
713300019	Site pic	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247230">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247230</a>