

State of Colorado
Energy & Carbon Management Commission



Document Number:
403528522

Date Received:
09/13/2023

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 6 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Arthur, Denise

denise.arthur@state.co.us

Laramie

cogccnotifications@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205100

Inspection Date: 07/14/2023

FIR Submit Date: 07/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 335647

Location Name: Cascade Creek (CC) Number: 0603-23-32 County: _____

Qtrqtr: NESW Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.548442 Longitude: -108.210463

FACILITY - API Number: 05-045- -00 Facility ID: 335647

Facility Name: Cascade Creek (CC) Number: 0603-23-32

Qtrqtr: NESW Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.548442 Longitude: -108.210463

CORRECTIVE ACTIONS:

3 CA# 175711

Corrective Action: Comply with 1002.f

Date: 10/17/2022

Response: CA COMPLETED

Date of Completion: 09/08/2023

Operator
Comment:

Culvert has been taken out of the 2A and is outside the disturbance area now.

COGCC Decision: _____

COGCC
Representative:

4 CA# 175712

Corrective Action: Comply with Rule 1002.f. Inspection #696204558 dated 12/27/2022 provided comment to the Operator that the silt fence was in disrepair; Operator failed to ensure BMP was repaired and/or maintained in proper functioning condition, therefore a CA date of 12/27/2022 is being provided,

Date: 12/27/2022

Response: CA COMPLETED

Date of Completion: 08/31/2023

Operator
Comment: Silt fence has been replaced (see Doc# 403523278)

COGCC Decision:

COGCC
Representative:

5 CA# 175713

Corrective Action: Comply with Rule 1002.b.(2). Coordinate with NW Reclamation Specialist so CECMC Staff are on site during segregation activities; topsoil will be required to be imported to supplement the topsoil resource lost.

Date: 07/14/2023

Response: CA COMPLETED

Date of Completion: 09/13/2023

Operator
Comment: Topsoil has been addressed in Doc # 403528405

COGCC Decision:

COGCC
Representative:

6 CA# 175714

Corrective Action: Comply with 1002.f and 1002.c

Date: 10/17/2022

Response: CA COMPLETED

Date of Completion: 09/12/2023

Operator
Comment: All stormwater issues have been addressed.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: _____

Title: Regulatory Specialist

Date: 9/13/2023 11:38:51 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403528573	CA Photos

Total Attach: 1 Files