

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403531004

Date Received:

09/14/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Luke Kelly

Phone

970-939-6353

Email

lkelly@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 709100060

Inspection Date: 07/13/2023

FIR Submit Date: 07/20/2023

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 424559

Location Name: Antelope Number: 43-17 County: WELD

Qtrqr: NESE Sec: 17 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.398320 Longitude: -104.340880

FACILITY - API Number: 05-123-00 Facility ID: 424568

Facility Name: Antelope Number: 33-17

Qtrqr: NESE Sec: 17 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.398320 Longitude: -104.340880

CORRECTIVE ACTIONS:

1 CA# 175963

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 08/14/2023

Response: CA COMPLETED

Date of Completion: 09/14/2023

Operator
Comment:

Operator reports that a ticket has been submitted for a dirt berm to comply with Rule 603.o. regarding secondary containment requirements.

COGCC Decision: _____

COGCC
Representative:

2 CA# 175964

Corrective Action: Comply with rule 606.c.

Date: 08/11/2023

Response: CA COMPLETED

Date of Completion: 09/14/2023

Operator Comment: Field has appropriately addressed the identified tumbleweeds and debris on location and have properly cleared/cleaned the area to comply with Rule 606.c.

COGCC Decision:

COGCC
Representative:

3 CA# 175965

Corrective Action: Install signs to comply with Rule 605.a.

Date: 08/14/2023

Response: CA COMPLETED

Date of Completion: 09/14/2023

Operator Comment: Operator has properly re-installed sign at tank battery. Additional matters regarding signage, including installing legible emergency contact number(s) on tanks, are currently being addressed to comply with Rule 605.a.

COGCC Decision:

COGCC
Representative:

4 CA# 175966

Corrective Action: Install sign to comply with Rule 605.(a)

Date: 08/14/2023

Response: CA COMPLETED

Date of Completion: 09/14/2023

Operator Comment: Operator reports that signage has been ordered and will be installed to comply with Rule 605.(a).

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

Due to errors brought on by ECMC's system changes and restructuring process, this Inspection Form was not delivered to the Field for processing before the Corrective Action Deadline. ECMC has confirmed that additional delays regarding Inspection Forms may persist and additional time has been granted to the Field to address the Corrective Action(s).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 9/14/2023 7:38:17 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403531009	Inspection Resolution Photos

Total Attach: 1 Files