



**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	overgrown vegetation		
Corrective Action	Comply with rule 606	Date:	09/25/2023

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	"Sign not legible Sign not updated to reflect current operator" Faded		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	09/25/2023

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	overgrown vegetation		
Corrective Action:	Comply with Rule 606	Date:	09/25/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	eletrical motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electrical panel		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 242191 Type: WELL API Number: 123-09982 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection flow line valves appear to be in the closed position.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 06/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Friday 8-25-2023 at approximately 10:00, I, Inspector Michael Kester, conducted an on-site inspection.                      Location: Mary Leinweber 1                      Operator: KPK                      API#: 123-09982                      County: Weld                      While there, I observed producing well that appeared to shut in at time of inspection. During this inspection the following possible compliance issues were observed:                      Weeds, Rule 606, corrective action date 9-25-2023, see photos 1, 2, 3, 4, 5, &amp; 6                      Sign, Rule 605g, corrective action date 9-25-2023, see photo 5                      Weather conditions: rainy and overcast                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC</p>	kesterm	08/25/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403526114	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247295">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247295</a>
713300050	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247246">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247246</a>