

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403511503

Date Received:
08/28/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dolezal, Pat</u>	<u>(970) 332-3585</u>	<u>pat.dolezal@ownresources.com</u>
<u>SCHNEIDER, ED</u>		<u>ed.schneider@ownresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200455
Inspection Date: 08/09/2023 FIR Submit Date: 08/15/2023 FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC Company Number: 10699
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 336838

Location Name: BARBER-65N46W Number: 8SWSE County: _____
Qtrqtr: SWSE Sec: 8 Twp: 5N Range: 46W Meridian: 6
Latitude: 40.411790 Longitude: -102.519310

FACILITY - API Number: 05-125-00 Facility ID: 336838

Facility Name: BARBER-65N46W Number: 8SWSE
Qtrqtr: SWSE Sec: 8 Twp: 5N Range: 46W Meridian: 6
Latitude: 40.411790 Longitude: -102.519310

CORRECTIVE ACTIONS:

1 CA# 178553

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management. Corrective action date is the date the location was observed out of compliance.

Date: 08/09/2023

Response: CA COMPLETED Date of Completion: 08/25/2023

Operator Comment: Well location was seeded and covered with straw

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed: _____

Title: Regulatory Specialist

Date: 8/28/2023 7:49:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403511503	FIR RESOLUTION SUBMITTED
403511506	Location Photo

Total Attach: 2 Files