

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2023

Submitted Date:

09/21/2023

Document Number:

702501894

**FIELD INSPECTION FORM**Loc ID 313094 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 10428

Name of Operator: DIVERSIFIED ENERGY LLC

Address: 19501 E MAIN STREET #200

City: PARKER State: CO Zip: 80138

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	(303) 894-2100, Ext 5164	conor.pesicka@state.co.us	
Haack, Denise	(303) 507-7437	dhaack@oagproduction.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Haack, Jason	(303) 719-4094	jhaack@oagproduction.com	

**General Comment:****ECMC Inspection Report Summary**

On Thursday, 09/21/2023, Inspector Kirby Burchett, attempted to conduct a follow up field inspection at Diversified Energy LLC on the Bingman 1-14 well, Location #313094, in Moffat County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

During this attempted inspection the following compliance issues were observed,

1. Access road gate locked.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location entrance sign with operator contact information. Called 303-995-0826 at 09:12 hours. 9 hours later still no response		
Corrective Action:	Provide key, combinations, or alternate method of access to comply with rule 204.	Date:	09/22/2023

Emergency Contact Number:

Comment: 303-995-0826

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501896	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260293">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260293</a>