

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403538217

Date Received:
09/22/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10797
Name of Operator: DESERT EAGLE OPERATING LLC
Address: 17101 PRESTON RD SUITE 105
City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
MARSHALL WESLEY		wmarshall@prohelium.com
CATHY BULF		cathybulf@gmail.com
Sanchez, Chris		chris.sanchez@state.co.us
BUTLER BRAD		butleroil@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 713600217
Inspection Date: 09/08/2023 FIR Submit Date: 09/11/2023 FIR Status:

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC Company Number: 10797
Address: 17101 PRESTON RD SUITE 105
City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 484359

Location Name: Red Rocks Number: 35-08 County: LAS ANIMAS
Qtrqr: NWSE Sec: 35 Twp: 29S Range: 55W Meridian: 6
Latitude: 37.471889 Longitude: -103.539533

FACILITY - API Number: 05-071-00 Facility ID: 484676

Facility Name: Red Rocks Number: 35-08
Qtrqr: NWSE Sec: 35 Twp: 29S Range: 55W Meridian: 6
Latitude: 37.471889 Longitude: -103.539533

CORRECTIVE ACTIONS:

1 CA# 180827

Corrective Action: Comply with Rule 905. for Management of E&P Waste. Date: 08/15/2023

Response: CA COMPLETED Date of Completion: 09/21/2023

In compliance with Rule 905,drill cuttings were placed on a bermed liner and covered with a tarp for dust control. Drill cuttings will be buried in a trench onsite, no transportation required.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 180828

Corrective Action: Comply with 1003 and 606.

Date: 09/13/2023

Response: CA COMPLETED

Date of Completion: 09/21/2023

Operator
Comment: Trash found on location has been removed.

COGCC Decision:

COGCC
Representative:

3 CA# 180829

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Conduct maintenance on equipment, cleanup stained material and review self
inspection processes. Implement or modify BMPs for improved material handling and
spill prevention.

Date: 09/08/2023

Response: CA COMPLETED

Date of Completion: 09/21/2023

Operator
Comment: Repair of BMs performed - Wattles were replaced. Areas of oil stained soil has been removed and will be brought
to an approved third party waste disposal facility. Review and update with peronnel of required daily review and
maintenance of equipment, cleanup of stained material, and self inspections processes was conducted.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Desert Eagle Operating has endeavored to comply with all ECMC Rules and Regulations at the Red Rocks 35--08
location and all locations it operates. Corrective action has been taken to ensure compliance to Rule 905 for
Management of E&P Waste. Per the approved Form 2, Drill cuttings will be buried onsite in trenches after the soil
analysis is complete and Form 27 is submitted and approved. Interim reclamation will be completed during the next
growing season and within six months of drilling operations.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and
complete.

Print Name: Cathy Buf

Signed: _____

Title: Manager

Date: 9/22/2023 9:40:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document
Number.

Document Number	Description
403538220	RR 35-08 Drill Cuttings Lined and Bermed
403538301	RR 35-08 Trash Removed
403538312	RR 35-08 Stained Soil Removed

Total Attach: 3 Files