

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/21/2023

Submitted Date:

09/21/2023

Document Number:

707901107

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
320504 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_ 46290 \_\_\_\_\_  
Name of Operator: KP KAUFFMAN COMPANY INC \_\_\_\_\_  
Address: 1700 LINCOLN ST STE 4550 \_\_\_\_\_  
City: \_\_\_\_\_ DENVER \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 80203 \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 \_\_\_\_\_ Number of Comments  
2 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271841	WELL	PR	11/01/2022	OW	001-09491	CUNDALL 6-12	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	Mechanical issue: 2" ball valve appears to be leaking fluid.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date:	09/26/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 271841 Type: WELL API Number: 001-09491 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 01/25/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: It appears fluid is leaking out of 2" ball valve on braden head.

Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b. Date: 09/26/2023

Reportable: YES GPS: Lat 39.981070 Long -104.951788

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Thursday September 21, 2023 at approximately 9:55AM, I, Inspector Randy Silver, conducted an on-site inspection.                      Location: Cundall #6-12                      Operator: KP Kauffman                      API#: 001-09491                      County: Adams                      While there, I observed producing well site                      During this inspection the following possible compliance issues were observed:                      Mechanical issue: Rule 608e corrective action date 9-22-23 see photos                      Spill: Rule 912 b corrective action date 9-22-23 see photos                      Weather conditions: Clear and dry                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p>	silverr	09/21/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901108	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263128">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263128</a>