

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

09/26/2023

Document Number:

699107462

**FIELD INSPECTION FORM**Loc ID 317489 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238228	WELL	PR	01/01/2023	GW	123-05061	SHOE 1	SI

**General Comment:**[This is a follow up to prior inspection document #699107168. CA's have not been corrected.](#)

**Location****Lease Road:**

Type	Access		
comment:	Access road is overgrown with vegetation and needs to be removed for good housekeeping. See attached photos.		
Corrective Action	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well sign does not reflect current operator. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.d	Date:	09/22/2023

**Emergency Contact Number:**

Comment:			
Corrective Action:			Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 238228 Type: WELL API Number: 123-05061 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 04/26/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 9/25/23 at approximately 1020hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document#699107168 at Shoe 1 of KP Kauffman Company Inc.</p> <p>API #05-123-05061 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Well sign does not reflect current operator. Install sign to comply with Rule 605.d. With a Corrective Action date of 9/22/23</p> <p>Access road is overgrown with vegetation and needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	09/26/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107463	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6264716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6264716</a>