

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403545085

Date Received:
09/28/2023

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

- 1 CA Completed
- 1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

Contact Name and Telephone:
 Name: _____
 Phone: () _____ Fax: () _____
 Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 707901107
 Inspection Date: 09/21/2023 FIR Submit Date: 09/21/2023 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 320504

Location Name: CUNDALL-61S68W Number: 12SEnw County: ADAMS
 Qtrqr: SEnw Sec: 12 Twp: 1S Range: 68W Meridian: 6
 Latitude: 39.981094 Longitude: -104.951842

FACILITY - API Number: 05-001- -00 Facility ID: 271841

Facility Name: CUNDALL Number: 6-12
 Qtrqr: SEnw Sec: 12 Twp: 1S Range: 68W Meridian: 6
 Latitude: 39.981094 Longitude: -104.951842

CORRECTIVE ACTIONS:

1 CA# 182097

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 09/26/2023

Response: CA COMPLETED Date of Completion: 09/26/2023

Operator Comment: Ball valve on bradenhead has been replaced.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2  CA# 182098

Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.

Date: 09/26/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment:

KPK crew was on site. It was just fresh water around the wellhead and the bradenhead had no flow and no pressure.

The inspection directs KPK to file a form 19, but since this wasn't a spill of production fluids KPK submits only the FIRR.

COGCC Decision: **Not Approved**

COGCC Representative:

Response denied due to lack of analyses documentation.

COGCC Supervisor:

Response denied due to lack of analyses documentation.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 9/28/2023 5:32:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403545085	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files