

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2023

Submitted Date:

09/25/2023

Document Number:

697008068

FIELD INSPECTION FORM

Loc ID 440858 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442121	WELL	EP	06/16/2017	LO	123-41687	Simpson FD 16-179HC	ND

General Comment:

Expired permit

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Other	# 1			
Comment:	Cellar ring remains on location, see attached photos.			
Corrective Action:	Remove cellar ring per Rule 406.(4)D.			Date: 10/31/2023

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 442121 Type: WELL API Number: 123-41687 Status: EP Insp. Status: ND**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 9/25/2023 at approximately 12:20 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Simpson FD 16-179HC API #123-41687 in Weld County, Colorado.</p> <p>While there, I observed that the cellar ring remained on location. The following possible compliance issues were observed: Rule 406(4)D. with a corrective action date of 10/31/2023.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	09/25/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403540668	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263415
697008069	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263411