

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

09/26/2023

Document Number:

699107462**FIELD INSPECTION FORM**Loc ID 317489 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238228	WELL	PR	01/01/2023	GW	123-05061	SHOE 1	SI

General Comment:[This is a follow up to prior inspection document #699107168. CA's have not been corrected.](#)

Location

Lease Road:			
Type	Access		
comment:	Access road is overgrown with vegetation and needs to be removed for good housekeeping. See attached photos.		
Corrective Action	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign does not reflect current operator. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.d	Date:	09/22/2023

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 238228 Type: WELL API Number: 123-05061 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 9/25/23 at approximately 1020hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document#699107168 at Shoe 1 of KP Kauffman Company Inc.</p> <p>API #05-123-05061 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Well sign does not reflect current operator. Install sign to comply with Rule 605.d. With a Corrective Action date of 9/22/23</p> <p>Access road is overgrown with vegetation and needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	09/26/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403542126	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6264721
699107463	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6264716