

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/05/2023

Document Number:

699107504

FIELD INSPECTION FORMLoc ID 327613 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
327613	LOCATION	AC			-	SEYFRIED-63N62W 1NWSW	AC

General Comment:[This is an inspection on the Tank Battery](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment next to the production tanks needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2023
Type	WEEDS		
Comment:	Overgrown vegetation throughout the location need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.249400,-104.274900	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 327613 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI Tank Battery

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary

burnsa

10/05/2023

On Tuesday 10/3/23 at approximately 0941hrs I, Inspector Adam Burns,
Conducted an on-site inspection at SEYFRIED-63N62W 1NWSW Tank Battery of KP
Kauffman Company INC.

Location Id: 327613 in Weld County, Colorado.

During this inspection the following possible compliance issues were observed:

Overgrown vegetation throughout the location need to be removed for good housekeeping.

Comply with Rule 606. With a Corrective Action date of 10/20/23

Unused Equipment next to the production tanks needs to be removed for good
housekeeping. Comply with Rule 606. With a Corrective Action date of 10/20/23

A follow up on this site inspection needs to be conducted to ensure the

compliance issues have been corrected to comply with ECMC rules.

This is a summary of the inspection report.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107505	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275474