

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

10/03/2023

Document Number:

709100117

**FIELD INSPECTION FORM**Loc ID 312193 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Hart, Dale	(719) 729-3391	dalehartwoc@fairpoint.net	All Inspections

**General Comment:**

This is an environmental inspection of the Arthur Edens #1 (API 075-06203) and the Arthur Edens location (Location ID 312193).

ECMC inspector Krystal Heibel arrived onsite on September 26, 2023, around 12:15 PM to perform an Environmental Inspection.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash (strips of metal, bucket, light bulb, empty fluid containers) located onsite		
Corrective Action:	Comply with Rule 606	Date:	10/12/2023
Type	STORAGE OF SUPL		
Comment:	Storage of supplies and equipment located onsite.		
Corrective Action:	Comply with Rule 606	Date:	10/12/2023
Type	WEEDS		
Comment:	Tumbleweeds located within secondary containment around wellhead.		
Corrective Action:	Comply with Rule 606	Date:	10/12/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Tank	<= 1 bbl	
Comment:	Stained soils observed around the thieves hatch, within the metal shed, and next to the separator.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 11/03/2023

In Containment: No

Comment:

☒ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	Wildlife protections devices not adequate. No netting around the secondary containment fluids next to the wellhead and next to the tank battery.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 10/13/2023
Type:	# 2		
Comment:	Unauthorized tube allowing discharge or disposal of oil, gas, E&P Waste, chemical substances, trash discarded equipment or other oil field waste next to meter shed beside the separator and within paint bucket.		
Corrective Action:	Prevent any unauthorized discharge		Date: 10/13/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403548962	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272420">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272420</a>
709100118	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272412">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272412</a>