

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107548

FIELD INSPECTION FORM

Loc ID 331882 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
331882	LOCATION	AC			-	LOST CREEK-63N62W 20NENE	AC

General Comment:

This is a follow up to prior inspection document #699107156. CA's were not corrected.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Pit needs capacity label. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/22/2023

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown vegetation around the tank battery needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Inspected Facilities

Facility ID: 331882 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI Tank Battery
No FIRR was submitted.

Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b

Date: 10/13/2023

COGCC Comments

Comment	User	Date
<p><u>ECMC Inspection Report Summary</u> On Monday 10/9/23 at approximately 0918hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107156 at Lost Creek-63N62W 20NENE Tank Battery of O'Brien Energy Resources Corp. Location ID #331882 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Pit needs capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23 Overgrown vegetation around the tank battery needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23 No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/13/23 No CA's were corrected A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	10/11/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107549	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281131