

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107550

**FIELD INSPECTION FORM**Loc ID 331746 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265349	WELL	SI	12/01/2019	DSPW	123-21237	NORTH LOST CREEK 11	SI

**General Comment:**[This is a follow up to prior inspection document #699107150. CA's were not corrected](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation around the well needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 265349 Type: WELL API Number: 123-21237 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI  
No FIRR was submittedCorrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.Date: 10/13/2023**BradenHead**Date of Last Brhd Test: 11/27/2021 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No updated annual BH test on file. Submit reports. Form 17 #403257048 indicates it was last tested on 12/9/20.09/22/2023Corrective Action: Submit reports as per Rule 419.

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 10/9/23 at approximately 0924hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107150 at North Lost Creek 11 of O'Brien Energy Resources Corp. API #05-123-21237 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed: Overgrown vegetation around the well needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>No updated annual BH test on file. Submit reports. Form 17 #403257048 indicates it was last tested on 12/9/20. Submit reports as per Rule 419. With a Corrective Action date of 9/22/23</p> <p>No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/13/23</p> <p>No CA's were corrected</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	10/11/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107551	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281132">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281132</a>