

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107556

FIELD INSPECTION FORMLoc ID 332047 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------------|-----------------------|---------------------------------|
| Forma, Joseph | 603-427-2099 x111 | joeforma@obenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 269876 | WELL | SI | 12/01/2019 | GW | 123-21760 | LOST CREEK 14 | SI |

General Comment:[This is a follow up to prior inspection document #699107146. CA's were not corrected.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Stained soil next to the well needs to be removed. See attached photo

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 09/22/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 269876 Type: WELL API Number: 123-21760 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI
No FIRR was submitted.

Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.

Date: 10/13/2023

BradenHead

Date of Last Brhd Test: 11/27/2021

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403256966 indicates it was last tested on 12/8/20.

09/22/2023

Corrective Action: Submit reports as per Rule 419.

Date:

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Monday 10/9/23 at approximately 0934hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107146 at Lost Creek 14 of O'Brien Energy Resources Corp.</p> <p>API #05-123-21760 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 9/22/23</p> <p>No updated annual BH test on file. Submit reports. Form 17 #403256966 indicates it was last tested on 12/8/20. Submit reports as per Rule 419. With a Corrective Action date of 9/22/23</p> <p>No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/13/23</p> <p>No CA's were corrected</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p> | burnsa | 10/11/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699107557 | Inspection Photos | http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281137 |