

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

10/05/2023

Document Number:

694100175

**FIELD INSPECTION FORM**Loc ID 323600 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Baker, Melissa	(970) 506-9272	melissa.baker@pdce.com	
,		cogccinspection@pdce.com	ALL INSPECTIONS
, PDC		cogccinspection@pdce.com	All Inspections

**General Comment:**

This is an environmental inspection for Location ID 323600 Conlin Federal, Holmes Federal pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

Comment: Trash/debris on site. Statewide unnecessary equipment, weeds, waste, and trash requirements

Corrective Action: Comply with Rule 606

Date: 10/19/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

Comment: Oily patch/stain on pad location.  
 Use when oily waste is E&P waste, especially around or in tank berms, load out lines. You can use this rule when you find small localized areas of oil/condensate staining that need to be cleaned up. Can always use in conjunction with 912.a. & b for reportable spills. DO NOT USE FOR REFINED OILS, USED OILS, OR DIESEL FUEL.

Corrective Action: "For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e.""

Date: 10/19/2023

For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS""

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: Seprator berm has damage from livestock.					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.					Date: 11/02/2023

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <input type="text"/>				



**Environmental****Spills/Releases:**

Type of Spill:	Estimated Spill Volume:
Comment:	Oily patch on site. See CA from Location tab.
Corrective Action:	Date:
Reportable:	GPS: Lat Long
Proximity to Surface Water:	Depth to Ground Water:

**Water Well Complaint:**

DWR Receipt Num:	Owner Name:	GPS :	Lat	Long
------------------	-------------	-------	-----	------

**Field Parameters:**

Sample Location:	Comment:
------------------	----------

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403552016	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275599">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275599</a>
694100176	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275568</a>