

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403559885

Date Received:

10/13/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 27742

Name of Operator: EOG RESOURCES INC

Address: P O BOX 4362

City: HOUSTON State: TX Zip: 77210-4362

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Cindy Vue

7206932446

cindy_vue@eogresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800614

Inspection Date: 08/29/2022

FIR Submit Date: 09/01/2022

FIR Status: _____

Inspected Operator Information:

Company Name: EOG RESOURCES INC

Company Number: 27742

Address: P O BOX 4362

City: HOUSTON State: TX Zip: 77210-4362

LOCATION - Location ID: 313287

Location Name: BAKERS PEAK STATE-611N91W Number: 12NWSE County: _____

Qtrqr: NWSE Sec: 12 Twp: 11N Range: 91W Meridian: 6

Latitude: 40.918502 Longitude: -107.551836

FACILITY - API Number: 05-081- -00 Facility ID: 313287

Facility Name: BAKERS PEAK STATE-611N91W Number: 12NWSE

Qtrqr: NWSE Sec: 12 Twp: 11N Range: 91W Meridian: 6

Latitude: 40.918502 Longitude: -107.551836

CORRECTIVE ACTIONS:

1 CA# 164273

Corrective Action: Comply with 1004 Rules. Conduct additional reclamation in accordance with COGCC 1000 series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be completed no later than 11/15/2022.

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 09/12/2023

Operator Comment: The gully and erosion in the center of the location was recontoured and reseeded September 12, 2023. Additional water bars were installed to help spread the water coming off the adjacent hillside. Site will be monitored to determine if additional seeding is required to achieve reclamation success.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 164274

Corrective Action: Comply with 1002.f. Implement and maintain stormwater and erosion control BMPs until long-term stabilization has been achieved and site has received a passing final reclamation inspection.

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 09/12/2023

Operator Comment: The gully and erosion in the center of the location was recontoured and reseeded September 12, 2023. Additional water bars were installed to help spread the water coming off the adjacent hillside. Site will be monitored to determine if additional seeding is required to achieve reclamation success.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to the attention of inspector Aaron Trujillo.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cindy Vue

Signed: _____

Title: Snr Regulatory Specialist

Date: 10/13/2023 8:43:26 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403559893	Pictures
-----------	----------

Total Attach: 1 Files