

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403548746

Date Received:
10/17/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 6 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10814
Name of Operator: MDS ENERGY DEVELOPMENT LLC
Address: 409 BUTLER RD SUITE A
City: KITTANNING State: PA Zip: 16201

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>SAADEH, RICHARD</u>		<u>richard.saadeh@mdsed.com</u>
<u>Jamie Jost</u>		<u>jjost@jostenergylaw.com</u>
<u>CHAPARRO, SIJI</u>		<u>logan.hansen@state.co.us</u>
<u>Jim Jacobsen</u>		<u>siji.chaparro@iptwell.com</u>
<u>Jim Jacobsen</u>		<u>jim.jacobsen@iptwell.com</u>
<u>Andrea Gross</u>		<u>agross@upstreampm.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200543
Inspection Date: 09/06/2023 FIR Submit Date: 09/15/2023 FIR Status: _____

Inspected Operator Information:

Company Name: MDS ENERGY DEVELOPMENT LLC Company Number: 10814
Address: 409 BUTLER RD SUITE A
City: KITTANNING State: PA Zip: 16201

LOCATION - Location ID: 477495

Location Name: Daffy Number: Pad County: _____
Qtrqr: NENW Sec: 33 Twp: 8N Range: 59W Meridian: 6
Latitude: 40.622725 Longitude: -103.985025

FACILITY - API Number: 05-123-00 Facility ID: 477495

Facility Name: Daffy Number: Pad
Qtrqr: NENW Sec: 33 Twp: 8N Range: 59W Meridian: 6
Latitude: 40.622725 Longitude: -103.985025

CORRECTIVE ACTIONS:

1 CA# 181253

Corrective Action: Install sign to comply with Rule 605.a. Corrective action date is the date the location was observed out of compliance.

Date: 09/06/2023

Response: CA COMPLETED

Date of Completion: 10/13/2023

Operator Comment: A sign that complies with Rule 605.a has been installed. Please see the attached photos.

COGCC Decision:

COGCC Representative:

2 CA# 181254

Corrective Action: Per Rule 1202.a.8, Operators will conduct pre-construction nesting migratory bird surveys within the approved disturbance area prior to any vegetation removal during the nesting season (April 1 to August 31). The Operator submitted report (doc #403506506) does not conform to the requirements of Rule 1202.a.8 based on the protocol performed in the report and that it was performed on 07/19/2023, after the location was approximately 95% constructed. This location is out of compliance with Rule 1202.a.8, and is being referred to Enforcement.

Date:

Response: CA COMPLETED

Date of Completion: 07/19/2023

Operator Comment: Operator will work with the enforcement group.

COGCC Decision:

COGCC Representative:

6 CA# 181258

Corrective Action: Comply with Rule 1002.f. Location will remain out of compliance until the corrective action has been resolved.

Date: 09/06/2023

Response: CA COMPLETED

Date of Completion: 09/06/2026

Operator Comment: Trash has been picked up from location. Regular inspections are taking place and good housekeeping BMPs are being maintained.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Construction will be completed by the week of October 23rd. The access road violations will be corrected and the FIRR for those will be submitted. Corrective Action #2 will be worked through the enforcement group.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Andrea Gross Signed:

Title: Permit Agent Date: 10/17/2023 1:09:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (http://ogccweblink.state.co.us/) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403563070	Photos

Total Attach: 1 Files