

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2023

Submitted Date:

10/19/2023

Document Number:

702501974

## FIELD INSPECTION FORM

Loc ID 314532 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10605  
 Name of Operator: APEX OIL VENTURES INC  
 Address: 8823 S. REDWOOD ROAD #D-1  
 City: WEST JORDAN State: UT Zip: 84088

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Callister, Andrew	(801) 455-8366	andy@qualityoilproperties.com	
Callister, Jan E	(808) 571-5890	jec-apex@outlook.com	
Rasmussen, Terry	(801) 487-4721	t.rasmussen1@outlook.com	

**General Comment:**[ECMC Inspection Report Summary](#)

On Wednesday, 10/18/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Apex Oil Ventures Inc on the P.R.-Trigood-Gov't 7, Location #314532, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Well has been Plugged & Abandoned. Wellhead removed, capped and backfilled.  
 Remaining debris and anchors to be removed during reclamation.

No follow up inspection is required.