

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 58-20 Pad
Location # 335135



**Location Overview: Location is within High Priority/Density
Habitat areas. Location is approximately 214 yards from a
creek/drainage that contributes to the Colorado River.**

Section/Township/Range: 20 6S94W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 58-20 Pad
Location # 335135



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.