

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403570452

Date Received:  
10/24/2023

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696305334

Inspection Date: 10/11/2023

FIR Submit Date: 10/11/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 422838

Location Name: Dutch Lake Pad Number: 16-24H County: \_\_\_\_\_

Qtrqr: NWN Sec: 24 Twp: 6N Range: 62W Meridian: 6  
W

Latitude: 40.479094 Longitude: -104.278358

#### FACILITY - API Number: 05-123-00 Facility ID: 422838

Facility Name: Dutch Lake Pad Number: 16-24H

Qtrqr: NWN Sec: 24 Twp: 6N Range: 62W Meridian: 6  
W

Latitude: 40.479094 Longitude: -104.278358

### CORRECTIVE ACTIONS:

1 CA# 184938

Corrective Action: Install sign to comply with Rule 605.h.

Date: 10/25/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator  
Comment:

Labels regarding Content, Capacity, and NFPA has been updated and installed to comply with Rule 605.h.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 184939

Corrective Action: Comply with Rule 606

Date: 10/27/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator  
Comment:

Operator has addressed and cleared overgrown vegetation and weed debris from location to comply with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 184940

Corrective Action: Comply with Rule 606

Date: 10/27/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator  
Comment:

Operator has marked the identified risers to comply with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**4** CA# 184941

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 10/27/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator  
Comment:

Operator has appropriately addressed and cleaned identified areas of stained soil to comply with Rule 905.e.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 10/24/2023 10:06:03 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403570476	Inspection Resolution Report

Total Attach: 1 Files