

**TEP Rocky Mountain LLC
Federal RGU 23-23-198
Location ID: 419254**



Chemical leaking on equipment and location



Unmarked anchor from previous inspection

**TEP Rocky Mountain LLC
Federal RGU 23-23-198
Location ID: 419254**



Location from Northwest corner



Location from Northeast corner

**TEP Rocky Mountain LLC
Federal RGU 23-23-198
Location ID: 419254**



Location from Southwest corner



Location from Southeast corner