

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2023

Submitted Date:

10/19/2023

Document Number:

699107628

**FIELD INSPECTION FORM**Loc ID 305083 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430745	WELL	PR	05/25/2014	OW	123-36277	Stonebraker 28V-404	TA

**General Comment:**[Form 05A on file](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>		
Type	OTHER	
Comment:	Stained soil around the well and prime mover needs to be removed. See attached photos	
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date: 10/31/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:	Panel	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 430745 Type: WELL API Number: 123-36277 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: T/A due to offset frac

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 06/19/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday 10/18/23 at approximately 1143hrs I, Inspector Adam Burns, Conducted an on-site inspection at Stonebraker 28V-404 of PDC Energy. API #05-123-36277 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil around the well and prime mover needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 10/31/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	10/19/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403566017	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291032">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291032</a>
699107629	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291027">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291027</a>