

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403573156

Date Received:
10/26/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Fischer, Alex

alex.fischer@state.co.us

Arauza, Steven

steven.arauza@state.co.us

Arthur, Denise

denise.arthur@state.co.us

. Laramie

cogccnotifications@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205144

Inspection Date: 08/04/2023

FIR Submit Date: 08/07/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 383264

Location Name: Cascade Creek (CC) Number: 0610-21-41 County: _____

Qtrqtr: NENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.544325 Longitude: -108.207010

FACILITY - API Number: 05-045- -00 Facility ID: 383264

Facility Name: Cascade Creek (CC) Number: 0610-21-41

Qtrqtr: NENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.544325 Longitude: -108.207010

CORRECTIVE ACTIONS:

1 CA# 177590

Corrective Action: Clean/remediated soils to Table 915-1 cleanup standards.

Date: 08/04/2023

Response: CA COMPLETED

Date of Completion: 08/08/2023

Spill ID is 484892. Stained soil has been addressed

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 177591

Corrective Action: Comply with Rule 1002.f and Form 2A COAs.

Date: 07/14/2023

This issue is now also being considered a Spill. Contact NW EPS Arauza, or EPS Supervisor Alex Fischer (alex.fischer@state.co.us) for Form 27 remediation, and possible Form 19 Spill reporting requirements, for areas beyond the Working Pad Surface of the Location impacted by drill cutting E&P waste; this issue is being considered for enforcement.

Response: CA COMPLETED

Date of Completion: 08/08/2023

Operator
Comment:

Spill ID is 484892

COGCC Decision:

COGCC
Representative:

3 CA# 177592

Corrective Action: Contact NW EPS Arauza (steven.arauza@state.co.us), or Western EPS Supervisor Alex Fischer (alex.fischer@state.co.us).

Date: 07/14/2023

Response: CA COMPLETED

Date of Completion: 08/08/2023

Operator
Comment:

Cuttings have been pushed off of working surface.

COGCC Decision:

COGCC
Representative:

4 CA# 177593

Corrective Action: Comply with Rules 606.c and 1002.c.

Date: 08/04/2023

Response: CA COMPLETED

Date of Completion: 10/25/2023

Operator
Comment:

Weeds have been sprayed, Laramie will continue to monitor the Noxious Weeds

COGCC Decision:

COGCC
Representative:

5 CA# 177594

Corrective Action: Comply with Rule 1002.f; install or repair required stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 08/04/2023

Response: CA COMPLETED

Date of Completion: 10/24/2023

Berms have been repaired.

Signed: _____

Date: 10/26/2023 7:30:42 AM