



MCCARTNEY ENGINEERING LLC
RICE #3
SENW SEC.33-T12N-R54W
EMERGENCY CALL 911 OR 303-916-4070

Latitude: 40.973051
Longitude: -103.414219
Elevation: 1383.55±3.57 m
Accuracy: 4.59 m
Time: 10-18-2023 12:00:26

NoteCam @ iOS



Latitude: 40.972997
Longitude: -103.414151
Elevation: 1384.26±3.57 m
Accuracy: 4.59 m
Time: 10-18-2023 12:01:02
Note: Unused equipment

NoteCam @ iOS



Latitude: 40.972998
Longitude: -103.414116
Elevation: 1385.33±3.57 m
Accuracy: 4.59 m
Time: 10-18-2023 12:01:13

NoteCam @ iOS




Latitude: 40.973011
Longitude: -103.414078
Elevation: 1383.45±3.29 m
Accuracy: 4.80 m
Time: 10-18-2023 12:01:21
Note: Fence

NoteCam @ iOS



Latitude: 40.973029
Longitude: -103.414083
Elevation: 1384.21±3.36 m
Accuracy: 4.75 m
Time: 10-18-2023 12:01:40
Note: Impacted material on soil



Latitude: 40.973018
Longitude: -103.414088
Elevation: 1384.11±3.37 m
Accuracy: 4.74 m
Time: 10-18-2023 12:01:54
Note: Impacted material on soil



Latitude: 40.973012
Longitude: -103.414044
Elevation: 1383.58±3.37 m
Accuracy: 4.74 m
Time: 10-18-2023 12:02:01
Note: No secondary containment

NoteCam @ iOS



Latitude: 40.973044
Longitude: -103.414014
Elevation: 1383.82±3.37 m
Accuracy: 4.74 m
Time: 10-18-2023 12:02:30
Note: Impacted material on soil



Latitude: 40.973069
Longitude: -103.414027
Elevation: 1383.45±3.37 m
Accuracy: 4.74 m
Time: 10-18-2023 12:02:48

NoteCam @ iOS



Latitude: 40.973057
Longitude: -103.414029
Elevation: 1382.78±3.38 m
Accuracy: 4.74 m
Time: 10-18-2023 12:02:53
Note: Equipment