



00650723

7-6-79

The Application(s) for Permit to Drill (OGCC Form 2) enclosed herewith cannot be processed at this time for the reason(s) stated below:

- No bond (*wrong bond form*) Bond not signed
- No filing fee (\$75) Filing fee check not signed
- Application for Permit to Drill (OGCC Form 2) not signed
- Letter of waiver from owners of offsetting lease(s)
- Location not in accordance with Rule 318 or Spacing Order(s)
- Location not clearly reported
- Incomplete item(s) number(s) on Application to Drill (OGCC Form 2)
- Name of proposed objective horizon or geological formation
- Other

Please correct and resubmit.

OIL & GAS CONSERVATION COMMISSION

correct bond form attach. Have it filed out correctly & return

STATE OF COLO.
OIL & GAS CONS. COMM.
1319 SHERMAN ST., Rm 721