

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/24/2023

Document Number:

697602203

FIELD INSPECTION FORMLoc ID 475322 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477437	SPILL OR RELEASE	CL	07/28/2021		-	Yoxall Farms Manifold	EI

General Comment:

This is an environmental inspection for Spill ID 477437 Yoxall Farms Manifold. Any corrective actions from previous inspections that have not been addressed are still applicable. Operator and contract environmental personnel were on location and were installing monitoring wells and soil borings at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds are overgrown on location.

Corrective Action: Comply with Rule 606.

Date: 10/31/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Spill/Remediation:**

Comment: Staining is visible within the excavation at the flowline. Odor is very strong. Monitoring wells and soil borings were being installed at the time of the inspection.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: 12/20/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403571533	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6296949
697602204	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6296944