

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403559885

Date Received:  
10/13/2023

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 27742  
Name of Operator: EOG RESOURCES INC  
Address: P O BOX 4362  
City: HOUSTON State: TX Zip: 77210-4362

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Cindy Vue</u>	<u>7206932446</u>	<u>cindy_vue@eogresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800614  
Inspection Date: 08/29/2022 FIR Submit Date: 09/01/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: EOG RESOURCES INC Company Number: 27742  
Address: P O BOX 4362  
City: HOUSTON State: TX Zip: 77210-4362

LOCATION - Location ID: 313287

Location Name: BAKERS PEAK STATE-611N91W Number: 12NWSE County: \_\_\_\_\_  
Qtrqtr: NWSE Sec: 12 Twp: 11N Range: 91W Meridian: 6  
Latitude: 40.918502 Longitude: -107.551836

FACILITY - API Number: 05-081-00 Facility ID: 313287

Facility Name: BAKERS PEAK STATE-611N91W Number: 12NWSE  
Qtrqtr: NWSE Sec: 12 Twp: 11N Range: 91W Meridian: 6  
Latitude: 40.918502 Longitude: -107.551836

CORRECTIVE ACTIONS:

1  CA# 164273

Corrective Action: Comply with 1004 Rules. Conduct additional reclamation in accordance with COGCC 1000 series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be completed no later than 11/15/2022.

Date: 11/15/2022

Response: CA COMPLETED Date of Completion: 09/12/2023

Operator Comment: The gully and erosion in the center of the location was recontoured and reseeded September 12, 2023. Additional water bars were installed to help spread the water coming off the adjacent hillside. Site will be monitored to determine if additional seeding is required to achieve reclamation success.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2  CA# 164274

Corrective Action: Comply with 1002.f. Implement and maintain stormwater and erosion control BMPs until long-term stabilization has been achieved and site has received a passing final reclamation inspection.

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 09/12/2023

Operator Comment: The gully and erosion in the center of the location was recontoured and reseeded September 12, 2023. Additional water bars were installed to help spread the water coming off the adjacent hillside. Site will be monitored to determine if additional seeding is required to achieve reclamation success.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to the attention of inspector Aaron Trujillo.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cindy Vue

Signed: \_\_\_\_\_

Title: Snr Regulatory Specialist

Date: 10/13/2023 8:43:26 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403559885	FIR RESOLUTION SUBMITTED
403559893	Pictures

Total Attach: 2 Files