

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403568939

Date Received:
10/23/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Laramie

cogccnotifications@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205263

Inspection Date: 09/19/2023

FIR Submit Date: 09/21/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 335647

Location Name: Cascade Creek (CC) Number: 0603-23-32 County: _____

Qtrqtr: NESW Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.548442 Longitude: -108.210463

FACILITY - API Number: 05-045-00 Facility ID: 335647

Facility Name: Cascade Creek (CC) Number: 0603-23-32

Qtrqtr: NESW Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.548442 Longitude: -108.210463

CORRECTIVE ACTIONS:

1 ☒ CA# 181742

Corrective Action: Comply with Rule 1002.f; install or repair control measures in accordance with good engineering practices.

Date: 08/04/2023

If Operator believes the sediment trap is appropriate in size to manage runoff from the Location, Operator will be required to provide engineering stormwater calculations showing control is adequate.

Response: CA COMPLETED

Date of Completion: 10/23/2023

CA has been addressed

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 ☒ CA# 181744

Corrective Action: Operator shall submit, attached to a Form 4 Sundry notice, calculations showing the amount of topsoil resource lost on the Location due to improper segregation activities.

Date: 07/14/2023

Response: CA COMPLETED

Date of Completion: 10/02/2023

Operator Comment: Form 4 Sundry has been filed, DOC# 403546862

COGCC Decision: Approved pending re-inspection

COGCC Representative: Sundry currently under review.

4 ☒ CA# 181745

Corrective Action: Comply with 1002.f and 1002.c

Date: 10/17/2022

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator Comment: CA has been addressed

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: _____

Title: Regulatory Specialist

Date: 10/23/2023 11:53:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403568939	FIR RESOLUTION SUBMITTED
403569066	CA Photos

Total Attach: 2 Files