

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403579533

Date Received:

11/01/2023

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Binschus, Chris</u>		<u>chris.binschus@state.co.us</u>
<u>Smith, Sydney</u>	<u>303-910-4511</u>	<u>SSmith@fundareresources.com</u>
<u>Parrish, Melissa</u>	<u>970-397-3896</u>	<u>MParrish@fundareresources.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 713900023

Inspection Date: 10/17/2023

FIR Submit Date: 10/19/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: FUNDARE RESOURCES OPERATING COMPANY LLC

Company Number: 10773

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

### LOCATION - Location ID: 436724

Location Name: Horsetail Number: 33M Pad County: \_\_\_\_\_

Qtrqr: SWS Sec: 33 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.789017 Longitude: -103.762128

### FACILITY - API Number: 05-123-00 Facility ID: 436724

Facility Name: Horsetail Number: 33M Pad

Qtrqr: SWS Sec: 33 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.789017 Longitude: -103.762128

### CORRECTIVE ACTIONS:

1 CA# 185529

Corrective Action: Comply with Rule 606.

Date: 10/17/2023

Corrective action date is the date of observation.

Response: CA COMPLETED

Date of Completion: 10/17/2023

Operator Comment: Tumble Weeds Were Removed From The Fenceline To Maintain Proper Housekeeping In Accordance With Rule 606 - Please See Attached Photo Documentation.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 185530

Corrective Action: Control and contain spills/releases, conduct maintenance on equipment and clean up per Rule 912.a. The corrective date is the date the location was observed out of compliance.

Date: 10/17/2023

Response: CA COMPLETED

Date of Completion: 10/20/2023

Operator Comment: Non-Produced Water Standing In Tank Berm Due To Low Spot In Tank Berm Was Sucked Up & Properly Disposed Of In Accordance With Rule 912.a. - In Addition, Pea Gravel Has Been Placed Within Tank Berm To Cover Liner & Prevent Standing Water From Stormwater Event In The Future - Please See Attached Photo Documentation.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Melissa Parrish

Signed: \_\_\_\_\_

Title: Production Compliance Reg

Date: 11/1/2023 3:36:21 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403579971	Horsetail 33M COGCC Corrective Actions Completed & Uploaded 11.01.2023
-----------	--

Total Attach: 1 Files