

OIL AND GAS CONSERVATION COMMISSION **DEPARTMENT OF NATURAL RESOURCES** **OF THE STATE OF COLORADO**

File in duplicate for Patented and Federal lands.
 File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
 Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry		5. LEASE DESIGNATION AND SERIAL NO. D-033804-b																
2. NAME OF OPERATOR Twin Arrow, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME																
3. ADDRESS OF OPERATOR P. O. Box 948, Rangely, Colorado 81648		7. UNIT AGREEMENT NAME																
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface NW NW SW Section 11 At proposed prod. zone		8. FARM OR LEASE NAME G & M																
14. PERMIT NO. unknown		9. WELL NO. 3																
15. ELEVATIONS (Show whether DF, RT, GR, etc.) approx. 5420' GR		10. FIELD AND POOL, OR WILDCAT Rangely, Mancos																
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 11-1N-102W-6th P.M.																
NOTICE OF INTENTION TO: <table style="width:100%;"> <tr> <td>TEST WATER SHUT-OFF <input type="checkbox"/></td> <td>PULL OR ALTER CASING <input type="checkbox"/></td> <td>WATER SHUT-OFF <input type="checkbox"/></td> <td>REPAIRING WELL <input type="checkbox"/></td> </tr> <tr> <td>FRACTURE TREAT <input type="checkbox"/></td> <td>MULTIPLE COMPLETE <input type="checkbox"/></td> <td>FRACTURE TREATMENT <input type="checkbox"/></td> <td>ALTERING CASING <input type="checkbox"/></td> </tr> <tr> <td>SHOOT OR ACIDIZE <input type="checkbox"/></td> <td>ABANDON <input checked="" type="checkbox"/></td> <td>SHOOTING OR ACIDIZING <input type="checkbox"/></td> <td>ABANDONMENT <input type="checkbox"/></td> </tr> <tr> <td>REPAIR WELL <input type="checkbox"/></td> <td>CHANGE PLANS <input type="checkbox"/></td> <td>(Other) <input type="checkbox"/></td> <td></td> </tr> </table>		TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>	FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>	SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT <input type="checkbox"/>	REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>		12. COUNTY Rio Blanco
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>															
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>															
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT <input type="checkbox"/>															
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>																
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) April 28 and 29, 1977		13. STATE Colorado																

Date of work April 28 and 29, 1977



00043956

This well was cleaned out to 3200' and found to be non-productive.

We intend to abandon it by setting a 100' cement plug at 3200', filling the hole with drilling mud to the bottom of the surface casing at 225', setting a cement plug at 225' to 175', filling with drilling mud, setting a cement plug at the top of the surface casing with 10 sacks of cement, and setting the dry hole marker in the top of the cement.

The location around the well will be cleaned of all trash and any disturbed areas reseeded.

DVR	
FJP	
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>
GCH	
CGM	

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE **Manager**

DATE **5-19-77**

(This space for Federal or State office use)

APPROVED BY [Signature]
 CONDITIONS OF APPROVAL, IF ANY:

TITLE **DIRECTOR**
O & G CONS. COMM.

DATE **MAY 25 1977**

X