

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2023

Submitted Date:

11/02/2023

Document Number:

713300255

**FIELD INSPECTION FORM**Loc ID 318935 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 52060

Name of Operator: M E III CORPORATION

Address: 2670 PIERCE ST

City: WHEAT RIDGE State: CO Zip: 80214

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ERNEST, SCOTT	303-279-4429	sernst1@hotmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Silver, Randy		randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242533	WELL	SI	09/01/2020	GW	123-10324	PERRY 3	SI

**General Comment:**

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	overgrown vegetation		
Corrective Action	Comply with Rule 606	Date:	09/23/2023

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/23/2023
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	overgrown vegetation		
Corrective Action:	Comply with Rule 606	Date:	09/23/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 Bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shared with crude tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:



**Inspected Facilities**

Facility ID: 242533 Type: WELL API Number: 123-10324 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection it appears flowline valves are in the closed position. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 09/23/2023

**BradenHead**

Date of Last Brhd Test: 12/21/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 20 Fluid Type:

End Surf Csg Pressure: 0

Comment: submit report

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 11-1-2023 at approximately 11:00, I, Inspector Michael Kester, conducted an on-site reinspection as per Doc #713300027.</p> <p>Location: Perry 3</p> <p>Operator: M E Ill Corp.</p> <p>API#: 123-10324</p> <p>County: Weld</p> <p>While there, I observed well with production site.</p> <p>At time of inspection it does not appear any corrective actions from previous inspection have been address.</p> <p>MIT, Rule 417, corrective action date 9-23-2023</p> <p>Signs, Rule 605h, corrective action date 9-23-2023 photo 5</p> <p>Weeds, site, Rule 606, corrective action date 9-23-2023 photo 1, 2, 3, 4, 5, &amp; 6</p> <p>Weeds, road, Rule 606, corrective action date 9-23-2023 photo 4</p> <p>Weather conditions: sunny and frozen</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p>	kesterm	11/01/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403582837	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307967">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307967</a>
713300256	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307964">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307964</a>