




00053573



Bonneville Fuels Corporation  
A Subsidiary of Bonneville Pacific Corporation



June 23, 1998

Mr. Richard T. Griebeling  
Director  
Colorado Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801  
Denver, Colorado 80203

RE: Request for Exception Location  
Federal #16-24-A-1N-103W (Proposed Well Location)  
600' FSL, 1936' FWL Section 16, T1N, R103W, 6<sup>th</sup> P. M.  
Rio Blanco Co., Colorado


Dear Sir:

Bonneville Fuels respectfully request's administration approval of an exception location in the Castlegate formation because of topographical reasons. This well location requires an exception to Rule 318 because it is located 1022' from the Federal #16-34-1N-103W. The Federal #16-34-1N-103W is located at 660' FSL 2310' FEL Sec. 16, T1N, R103W and is operated by Bonneville Fuels Corporation. The proposed well is located 600' from the nearest lease line and does not encroach upon any offset leases.

Enclosed with this request is a map showing the approximate locations of the affected wells and lease boundaries.

If you have any questions or require anything further to process this request; please contact the undersigned at (303) 863-1555 ext. 233.

Very Truly Yours,

  
Thomas E. Bowman  
Operations Manager

enclosure