

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403605751

Date Received:  
11/24/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
Luke Kelly 970-939-6353 lkelly@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696305384  
Inspection Date: 11/07/2023 FIR Submit Date: 11/09/2023 FIR Status:

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452726

Location Name: Anschutz-Williams Number: 5-61-27 SWSW County:  
Qtrqr: SWS Sec: 27 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.366717 Longitude: -104.203547

FACILITY - API Number: 05-123-00 Facility ID: 452726

Facility Name: Anschutz-Williams Number: 5-61-27 SWSW  
Qtrqr: SWS Sec: 27 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.366717 Longitude: -104.203547

CORRECTIVE ACTIONS:

1 CA# 188075

Corrective Action: Install sign to comply with Rule 605.h. Date: 11/24/2023

Response: CA COMPLETED Date of Completion: 11/15/2023

Operator Comment: Identified Condensate Vaults have been appropriately addressed by the Operator to ensure that the proper signage is up to date and visible to comply with Rule 605.h.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 188076

Corrective Action: Comply with Rule 606

Date: 11/24/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator  
Comment:

Operator has removed identified locate flags on location to comply with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 188077

Corrective Action: Install Temporary or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

Date: 11/24/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator  
Comment:

Operator has installed material to close open separators to prevent unauthorized discharge to comply with Rule 902.b.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**4** CA# 188078

Corrective Action: Comply with Rule 606

Date: 11/24/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator  
Comment:

The Operator has addressed and cleared identified tumbleweed debris to comply with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 11/24/2023 5:42:20 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403605757	Inspection Resolution Report

Total Attach: 1 Files